

July 13, 1972

Mr. A. M. Ferenz
Columbia Gas Transmission
Corporation
P.O. Box 1273
Charleston, West Virginia 25320

Dear Mr. Ferenz:

This is in further response to your telephone conversation with our Mr. Paul Cory on July 3, 1972, regarding the definition of property damage in Subpart 10 in the leak and test failure report Form DOT F-7100.2.

The instructions for completing Form DOT F-7100.2-1 dated November 17, 1971, instructed operators that the definition of "property damage" will include the cost of material labor and equipment to repair the leak and estimated cost of gas lost. This definition of property damage should also be used in the leak and test failure report form DOT F-7100.2 or any other report or communication regarding the gas pipeline safety regulations.

We trust that this has answered your particular question. If we can be of further assistance, please let us know.

Sincerely,

Cesar DeLeon
Operation & Compliance Officer
Office of Pipeline Safety